

TECHNICAL BULLETIN



March 18, 2013 • TB0313-18

Rev May 15, 2013

UPP Discontinued Elbows

Franklin Fueling Systems is announcing the discontinuation of three parts. These parts had been used to create double wall (Secondary Contained) 45° and 90° joints in 90/160 mm and 110/160 mm pipework.

Discontinued Parts

UL part number	Joint created
03-090-LS-4-U	3" 90° double wall
04-090-LS-4-U	3" 45° double wall
04-110-LS-4-U	4" 45° double wall

If your installation requires one of these fittings, please contact Franklin Fueling Systems Technical Support at 1-800-984-6266 for the appropriate alternative.

DRAFT